

**Table 1:** Frequency of changes in the pacemaker settings at follow-up visits.

Changes in PM settings	n (%)
Stimulation threshold - Right ventricle	242 (16.87)
Stimulation threshold - Atrial	208 (14.05)
Sensing threshold - Right ventricle	188 (13.11)
Sensing threshold - Atrial	177 (12.34)
Mode change	183 (12.76)
Sensor turned ON	67 (4.67)
Sensor turned OFF	61 (4.25)
Maximum sensor rate	84 (5.86)
A-V Delay	102 (7.11)
Pulse duration	68 (4.74)
Mode switch (on-Off)	54 (3.76)
Overall	1,434

PM: pacemaker, n: number.